

Prepared for: DCOR, LLC

290 Maple Court Suite #290

Ventura, CA 93003 Attn: Jay Rao

Report Date: Octo

October 10, 2016

Laboratory Number: 162219

Project Name: PF Hillhouse Produced Water-Monthly

Sampled by: Ken Hindman

Enclosed are the analysis results for samples received October 3, 2016 with the Chain of Custody document. The sample was received in good condition, at 6° C, and it was identified and assigned the laboratory ID number listed below:

SAMPLE DESCRIPTION

CAS LAB NUMBER ID

Produced Water

162219-01

By my signature below, I certify that the results contained in this laboratory report comply with applicable standards for certification by the California Department of Public Health's Environmental Laboratories Accreditation Program (ELAP), both technically and for completeness, and that, based on my inquiry of the person or persons directly responsible for performing the analyses, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete.

Lance Lewy-Laboratory Director

If you have any further questions or concerns, please contact me at your convenience. This report consists of 1 page excluding the cover letter and the Chain of Custody.

This report shall not be reproduced except in full without the written approval of CAS. The test results reported represent only the item being tested and may not represent the entire material from which the sample was taken.

Environmental and Analytical Services-Since 1994 California State Accredited Laboratory in Accordance with ELAP Certificate # 2332

CERTIFICATE OF ANALYSIS

Client: DCOR, LLC (PF Hillhouse)

CAS LAB NO: 162219

Analyst: AN

Date Sampled: 10/03/16

Date Received: 10/03/16

Date Analyzed: 10/08/16 Sample Matrix: Water

SALINITY EPA Method SM 210C

CAS Lab #	Sample ID	RESULTS (g/Kg)	Dilution Factor	PQL (g∕Kg)
162219-01	Produced Water	20.0	1	1.0

QUALITY CONTROL REPORT

162219-MB Method Blank

BQL

1

1.0

g/Kg: grams/Kilograms

PQL: Practical Quantitation Limit BQL: Below Quantitation Limit

												J		7		,		_						
		Verified by	Print Name:	Relinquished by	Print Name:	Relinquished by Hong						1 10/3	Sample Date NO. Sampled	Print Name:	SAMPLER'S SIGNATURE		PHOJ. NO.		CHAIN OF C	(805) 644-10	Ventura, CA 93003	1536 Easiman Avenue	CEDWICES	つっロつ
	Print Name:	Verified by Lead Operator:(Signature)	1 Canapole	YN ::	HART	/ :(Signature)				-		36:00		大田乙 エ	GNATURE				CHAIN OF CUSTODY RECORD	(805) 644-1095 Fax 644-9947	93003	an Avenue	ANALYIN	
		วr:(Signature)	77 Time	の-子-16	7:00	Date 10-3-110						×	Comp Grab	HINDRARY	del	Produced W	Hillhouse	200	CORD	947			AL	:
)	Time	Date	Print Name:	Received by	Print Happio	Received by (Rignature))					Produced Water	Sample Description			Produced Water-Monthly	Hillhouse	Phone: 805 535-2078		Address	Company	Fax	BEDORT:	
		·	veytskin		Asvica							×	Water Soil Sludge Other Tyl	Matrix	A=Amber Bottle, G=C P=Plastic, V=Vial, O=Other	INER TY		Contact: Jay Rao	Ventura CA, 93003	290 Maple Court. Suite 290	DCOR,LLC.	(805) 535-2075		
48Hr 72Hr	24Hr.		Print Name:	Relinquishe	Printiplame:	ւ լ						70	Type	1A	ther cally				۵		Con	P.O. #	B E	
		1		gnature)	Jame: Officer	naushed the (Signature)						×			Salini					Address	Company:	#	BILL TO:	
Standard X other	5 day	Turn Around time	Time	Date	S Time	10 3 /16												_			DCOR,LLC.			
		ne	Print Name:	Received by :(Signature)	Print Name: Loyd Leonando		Dispose samples Return samples	CHECK ONE BOX			-	Produced Water Temp: 80	Remarks				10/10/10/11							

De Ste

de